

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)
(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Name of the Officer
2. Name of the School
3. Location with name of Education District/ Sub. District
4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

5. Period for which the certificate is issued
6. Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance works have been done properly
9. Whether the structure is sound or not for conducting classes

Shahrubh KV
Sheee Bhavarohi English
kanila, Manjeshwar medium school
Kandagad

- ~~29.9 x 6.25 x 3.60~~ office lab
- ① 6.10 x 6.02 x 3.60 (R.C.C)
 - ② 6.00 x 6.07 x 3.60 (R.C.C)
 - ③ 6.10 x 6.07 x 3.60 (R.C.C)
 - ④ 6.05 x 6.07 x 3.60 (R.C.C)
 - ⑤ 2 x 6.10 x 6.07 x 3.60 (R.C.C)
 - ⑥ 2 x 6.05 x 6.07 x 3.60 (R.C.C)
 - ⑦ 6.07 x 3.03 x 2.40 (R.C.C)
 - ⑧ 51.75 x 1.77 m (Vaganethe)
 - ⑨ 2 x 6.07 x 6.07 x 3.60 (R.C.C)
 - ⑩ 6.10 x 6.07 x 3.60 (R.C.C)
 - ⑪ 6.07 x 3.08 x 3.60 (R.C.C)
 - ⑫ 9.80 x 3.65 x 2.40 (R.C.C)
 - ⑬ 25.50 x 8 x 3.60 (Sheet)
 - ⑭ 2 x 6.10 x 6.10 x 3.60 (Lab Building)

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

Yes
The structure is safe for
conducting classes under normal
weather conditions

CERTIFICATE

certified that the school building was inspected by me on 1/06/23 and found to be fit / unfit to conduct classes, for the period 2023-24 for the reasons stated above.

Place: Manjeshwar
Date: 1/06/23

(Seal)

Manjeshwar
LSGD Section
Assistant Engineer

(Signature)

Assistant Engineer

